determined by the precision of the mold, which is manufactured to tolerances of +/- .003. The products can be made fast and economically using this process. Retaining wall product are dry stacked as opposed to using mortar between the joints. The tolerances have to be very close for the heights of the units. My design allows for these closer tolerances.